

\* 179/14 - CARTAS NÁUTICAS DO INSTITUTO HIDROGRÁFICO –  
CN 11101 – Correções

Na CN 11101, proceder às seguintes correções:

Inserir	cabo submarino		, unindo:	39°40,2'N / 031°06,5'W ; 39°37,7'N / 031°05,7'W ; 39°33,6'N / 031°01,5'W ; 39°31,7'N / 031°01,5'W ; 39°27,8'N / 031°07,5'W .
	cabo submarino		, unindo:	39°00,6'N / 027°57,5'W ; 38°55,6'N / 028°02,8'W ; 38°55,6'N / 028°06,7'W ; 39°02,9'N / 028°19,8'W ; 39°04,9'N / 028°36,6'W ; 39°09,5'N / 028°58,9'W ; 39°19,4'N / 029°16,7'W ; 39°21,1'N / 029°37,7'W ; 39°21,0'N / 029°45,9'W ; 39°25,7'N / 030°08,4'W ; 39°31,0'N / 030°21,4'W ; 39°31,9'N / 030°25,2'W ; 39°32,5'N / 030°50,5'W ; 39°33,7'N / 030°56,5'W ; 39°40,2'N / 031°06,8'W .
	cabo submarino		, unindo:	39°28,2'N / 031°07,2'W ; 39°25,4'N / 030°56,2'W ; 39°19,5'N / 030°51,0'W ; 39°00,6'N / 030°48,2'W ; 38°46,8'N / 030°34,5'W ; 38°37,8'N / 030°17,2'W ; 38°35,7'N / 030°01,7'W ; 38°35,9'N / 029°55,2'W ;
Inserir	cabo submarino (cont.)		, unindo:	38°32,4'N / 029°44,3'W ; 38°32,3'N / 029°34,1'W ; 38°28,4'N / 029°06,7'W ; 38°24,6'N / 028°54,5'W ; 38°28,4'N / 028°48,6'W ; 38°27,9'N / 028°42,3'W ; 38°30,8'N / 028°37,8'W .

CN afetada – 11101 [238/12;370/13]  
CEN afetada – PT111101 [102/14;102/14]  
Origem – Instituto Hidrográfico