

*** 148/13 - ATLÂNTICO NORTE – PORTUGAL – PORTUGAL CONTINENTAL – COSTA SUL –
Lagos – Culturas marinhas – Assinalamento marítimo**

Aviso cancelado – ANAV 223/13

Nas CN 24205 (INT 1817), e CN 24P05, proceder às seguintes correções (Datum Europeu):

Inserir		Boia A Fl(4)Y.12s3M	, em:	37°04,28'N / 008°41,64'W.
		Boia B Fl(4)Y.12s3M	, em:	37°04,28'N / 008°40,92'W.
		Boia C Fl(4)Y.12s3M	, em:	37°03,48'N / 008°40,92'W.
		Boia D Fl(4)Y.12s3M	, em:	37°03,48'N / 008°41,64'W.

Inserir	limite de viveiro	— — — — —	, unindo:	37°04,28'N / 008°41,64'W; 37°04,28'N / 008°40,92'W; 37°03,48'N / 008°40,92'W; 37°03,48'N / 008°41,64'W;
---------	-------------------	-----------	-----------	--

Inserir			, em:	37°03,89'N / 008°41,26'W.
---------	---	--	-------	---------------------------

CN 24206 (INT 1818), CN 24P06 e CN 25R11 proceder às seguintes correções (WGS84):

Inserir		Boia A Fl(4)Y.12s3M	, em:	37°04,20'N / 008°41,72'W.
		Boia B Fl(4)Y.12s3M	, em:	37°04,20'N / 008°41,00'W.
		Boia C Fl(4)Y.12s3M	, em:	37°03,40'N / 008°41,00'W.
		Boia D Fl(4)Y.12s3M	, em:	37°03,40'N / 008°41,72'W.

Inserir	limite de viveiro	— — — — —	, unindo:	37°04,20'N / 008°41,72'W; 37°04,20'N / 008°41,00'W; 37°03,40'N / 008°41,00'W; 37°03,40'N / 008°41,72'W;
---------	-------------------	-----------	-----------	--

Inserir			, em:	37°03,81'N / 008°41,34'W.
---------	---	--	-------	---------------------------

Na Lista de Luzes, Boias, Balizas e Sinais de Nevoeiro, Vol I, substituir a página 143/144, pela contida na Secção VII.

CN afetadas	– 24205 (INT 1817) [236/05;366/12], 24206 (INT 1818) [101/07;113/13], 24P05 [238/05;366/12], 24P06 [373/06;113/13], 25R11 [104/08;366/12]
CEN afetada	– PT324205 [195/09;381/12(P)]
PN afetada	– <i>Lista de Luzes, Boias, Balizas e Sinais de Nevoeiro, Vol I, 2011</i> [446.5], [446.6], [446.7], [446.8]
Origem	– Capitania do Porto de Lagos