

*** 193/17(T) - ATLÂNTICO NORTE – PORTUGAL – PORTUGAL CONTINENTAL – COSTA SUL –
Cabo de S. Vicente – Sinal sonoro inoperativo**

Aviso cancelado – ANAV 1312/17

Sinal sonoro Farol Cabo de S. Vicente, 37°01,37'N / 008°59,79'W (WGS 84), inoperativo.

- CN afetadas** – 11101 [238/12;187/15], 21101 (INT 1081) [247/02;129/16], 23203 (INT 1811) [312/06;130/16], 23204 (INT 1812) [131/02;145/16], 24205 (INT 1817) [236/05;191/17], 24206 (INT 1818) [101/07;191/17], 27502 [219/99;191/17], 61101 (INT 104) [202/13;282/15], 24P05 [238/05;191/17], 24P06 [373/06;191/17], 25R10 [272/06;138/16], 25R11 [104/08;191/17]
- CEN afetadas** – PT111101 [102/14;269/15], PT221101 [131/14;165/16(T)], PT324205 [195/09;191/17], PT528515 [225/07;290/15(T)]
- PN afetada** – *Lista de Luzes, Boias, Balizas e Sinais de Nevoeiro, Vol I, 2013* [436 (D-2168)]
- Origem** – Capitania do Porto de Lagos