

* 358/12 - CARTAS NÁUTICAS DO INSTITUTO HIDROGRÁFICO –
CN 25R07 – Correções

Na CN 25R07, proceder às seguintes correções (WGS 84):

Inserir	cabo submarino,  , unindo:	38°34.34'N / 009°11.71'W; 38°31.49'N / 009°26.43'W; 38°31.29'N / 009°28.22'W; 38°30.94'N / 009°29.64'W; 38°30.79'N / 009°30.69'W; 38°30.00'N / 009°32.51'W; 38°27.53'N / 009°34.68'W; 38°27.08'N / 009°35.25'W; 38°26.31'N / 009°36.72'W; 38°24.55'N / 009°39.06'W; 38°23.59'N / 009°40.05'W; 38°23.00'N / 009°40.58'W;
	área de cabos submarinos   , unindo:	38°34.57'N / 009°12.01'W; 38°31.59'N / 009°28.23'W; 38°30.98'N / 009°28.23'W; 38°34.01'N / 009°11.74'W.
	área de cabos submarinos   , unindo:	38°36.66'N / 009°13.01'W; 38°36.38'N / 009°23.00'W; 38°33.89'N / 009°23.00'W; 38°36.08'N / 009°12.67'W.

CN afetada – 25R07 [271/06;324/12]

Origem – Instituto Hidrográfico